Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2010 Mazda Motor of America, Inc.

Subject:

ENGINE OIL FLUSHING PROCEDURE

Last Issued: 07/13/2010

APPLICABLE MODEL(S)/VINS

2004-2010 RX-8

DESCRIPTION

When the rotary engine is replaced because of smoke from tailpipe or internal engine noise, an oil flushing procedure needs to be done if **metal particles are found in the engine oil.** This is to remove metal particles from the oil cooler and the oil lines.

To see if there are metal particles in the engine oil, stir the drained oil with a latex protected finger or a stick. If a "marble pattern" can be seen, the oil is contaminated with metal particles.



REPAIR PROCEDURE

- 1. After installing the new engine in the vehicle, fill it with new oil and install a new oil filter.
- 2. Start the engine and let it idle for at least 10 minutes.
- 3. Turn the engine off and let it cool down.
- 4. Drain the engine oil and replace the oil filter with a new one.
- 5. Refill the engine with new oil flushing completed.

Bulletin No: 01-041/10	Last Issued: 07/13/2010
© 2010 Mazda Motor of America, Inc.	

PART(S) INFORMATION

Part Number	Description	Qty.
0000-77-5W30-QT	Engine Oil (5W-20)	6 quarts
B6Y1-14-302A	Oil filter	2004-2008
N3R1-14-302	Oil filter	2009-2010

WARRANTY INFORMATION

NOTE:

- Please add labor operation XXF2CXRX for 0.2 hours to the Rotary Engine replacement claim for Flushing.
- This labor Operation is only applicable to the conditions described in this bulletin and applicable only to the 2004 to 2010 RX8.
- Do not submit as a separate claim problem. The time must have separate time punch on the repair order.