

Service Information

Mazda Motor Corporation

3-1, Shinchi, Fuchu-cho, Aki-gun
Hiroshima 730-8670, Japan
TEL : 81(82)287-5323
FAX : 81(82)287-5220



Category T	Technical	Ref. No. E019/11	Page 1 of 1
Coverage Distributor only Please inform your dealers		Date Issued September 12, 2011	
Please convey this information to your Warranty Dept. Parts Dept. Training Dept. Field Rep.		Date Revised	
Applicable Model All models		Applicable Countries or Specifications Worldwide	


Subject: Headlamp inner condensation due to improper socket covers installation

DESCRIPTION

When dealing with customer complaints of excessive condensation and/or water within the headlamp unit, first determine if all the bulb sockets are present and correctly installed.

In some cases you may find that the Bulb Seal No. 1 (A) or HID Bulb Seal No. 1 (B) and Bulb Seal No. 2 (C) socket covers have not been correctly installed or are missing due to improper prior repairs (i.e., customer replacing the headlamp bulbs or body shop not transferring them when replacing the headlamp unit(s) due to a collision).

Any damage caused by missing/incorrect installation of above mentioned socket covers, HID module seal (D), or missing bumper brackets (E) is not covered by warranty.



Shinji Kanai
Manager, Technical Information Gr.
Technical Service Dept.
Mazda Motor Corporation