

# Service Information

Mazda Motor Corporation

3-1, Shinchi, Fuchu-cho, Aki-gun  
Hiroshima 730-8670, Japan  
TEL : 81(82)287-5323  
FAX : 81(82)287-5220





Category <b>F</b>	<b>Technical</b>	Ref. No. E053/12	Page 1 of 1
Coverage <input type="checkbox"/> Distributor only <input checked="" type="checkbox"/> Please inform your dealers		Date Issued December 3, 2012	
Please convey this information to your <input type="checkbox"/> Director <input checked="" type="checkbox"/> General Manager <input checked="" type="checkbox"/> Warranty Dept. <input checked="" type="checkbox"/> Parts Dept. <input checked="" type="checkbox"/> Training Dept. <input checked="" type="checkbox"/> Field Rep.		Date Revised	
Applicable Model Mazda6 (GJ) with SKYACTIV-D 2.2		Applicable Countries or Specifications Worldwide	

## Subject: Noise Insulator on Vacuum Chamber and Turbocharger Bracket


### DESCRIPTION

On Mazda6 (GJ) with SKYACTIV-D 2.2 the vacuum chamber and the turbocharger bracket are wrapped by a cloth to insulate the operating noise. This is not a waste cloth!  
Be careful not to take off this noise insulator cloth by mistake.

[Vehicles under-surface]



Vacuum chamber



Mitsunori Tokunaga  
Manager, Technical Information Gr.  
Technical Service Dept.  
Mazda Motor Corporation