

# Service Information

Mazda Motor Corporation

3-1, Shinchi, Fuchu-cho, Aki-gun  
Hiroshima 730-8670, Japan  
TEL : 81(82)287-5323  
FAX : 81(82)287-5220



Category <b>T</b>	<b>Repair Guidance</b>	Ref. No. R079/12	Page 1 of 2
Coverage <input type="checkbox"/> Distributor only <input checked="" type="checkbox"/> Please inform your dealers		Date Issued November 6, 2012	
Please convey this information to your <input type="checkbox"/> Director <input checked="" type="checkbox"/> General Manager <input checked="" type="checkbox"/> Warranty Dept. <input checked="" type="checkbox"/> Parts Dept. <input checked="" type="checkbox"/> Training Dept. <input checked="" type="checkbox"/> Field Rep.		Date Revised <b>March 25, 2013</b>	
Applicable Model  CX-5 (KE) with rear mount camera	Applicable Countries or Specifications  Worldwide		

**Note: Part no. has been updated**

## Subject: Rear mount camera does not operate

### DESCRIPTION

Some vehicles may exhibit that the rear mount camera does not operate.

### CAUSE

This concern is caused by water entering inside the camera, e.g. during car washing with high-pressure cleaner.

### MASS PRODUCTION CHANGE

Shape of the camera has been changed.

### BEGINNING VIN & DATE OF MODIFICATION

#### **ADR spec**

JM0 KE \*\*\*\*\* 127897 October 7, 2012

#### **Algerian spec**

KE \*\*\*\* 127897 October 7, 2012

#### **Chinese spec**

JM7 KE \*\*\*\*\* 127897 October 7, 2012

#### **General spec**

JM6 KE \*\*\*\*\* 127897 October 7, 2012

JM8 KE \*\*\*\*\* 127897 October 7, 2012

#### **Israel spec**

JMZ KE \*\*\*\*\* 127897 October 7, 2012

#### **EU spec**

JMZ KE \*\*\*\*\* 141005 October 11, 2012

#### **US spec**

JM3 KE \*\*\*\*\* 155008 October 7, 2012

### REPAIR PROCEDURE

When you encounter a customer complaint on this concern, inspect the rear mount camera according to the Workshop Manual "REAR MOUNT CAMERA INSPECTION".

If the rear mount camera is found to be faulty, replace it with a modified one following the procedure in the Workshop Manual "REAR MOUNT CAMERA REMOVAL/INSTALLATION".

PART INFORMATION

Part Number		Part Name	Q'ty	Remark
New	Old			
KD45 67 RC0C	KD45 67 RC0B	Rear mount camera	1	For EU
KD33 67 RC0A	KD33 67 RC0		1	For other market

WARRANTY INFORMATION

Assembly group	T – Body Electrical
Subassembly group	05 - WARNING SYSTEM
Symptom Code	61
Damage Code	9K
Causal Part No.	KD33 67 RC0B or KD45 67 RC0C (Rear mount camera)
Q'ty	1
Operation No. & Labor Hours	XXH8FXRX & 0.5H (for EU) XXH8GXRX & 0.4H (for other market)
Period Covered	Normal warranty period

Mitsunori Tokunaga  
Manager, Technical Information Gr.  
Technical Service Dept.  
Mazda Motor Corporation  
2C31311234 (MC Internal Use)