

Service Information

Mazda Motor Corporation

3-1, Shinchi, Fuchu-cho, Aki-gun
Hiroshima 730-8670, Japan
TEL : 81(82)287-5323
FAX : 81(82)287-5220



Category N	Repair Guidance	Ref. No. R067/13 ^Ó	Page 1 of 6
Coverage <input type="checkbox"/> Distributor only <input checked="" type="checkbox"/> Please inform your dealers		Date Issued August 28, 2013	
Please convey this information to your <input type="checkbox"/> Director <input checked="" type="checkbox"/> General Manager <input checked="" type="checkbox"/> Warranty Dept. <input checked="" type="checkbox"/> Parts Dept. <input checked="" type="checkbox"/> Training Dept. <input checked="" type="checkbox"/> Field Rep.		Date Revised June 12, 2014	
Applicable Model Mazda6(GJ), CX-5(KE), Mazda3(BM)		Applicable Countries or Specifications Worldwide	

REVISED

This Service Information supersedes R070/13

Subject: Unusual noise when vehicle is started with steering wheel fully turned to driver-side

MOVIE FILE WITH NOISE SAMPLE