



M-TIPS



2004 RX-8

ABS/TCS Light ON/Lack Of Power

Some customer may complain of the ABS and/or TCS light on, and a lack of power at times. The ABS/TCS may or may not store DTCs, and the concern may occur after tire replacement. The cause may be due to a difference in tire diameter because of the following situations:

- Worn and new tires installed on the vehicle at the same time.
- Mismatched tires from different manufacturers installed on the vehicle.

Before attempting any repairs:

- Verify tire condition, brand, and size.
- Consult with customer regarding wear & mismatched brands/sizes.