

MULTI-MODEL EXCESSIVE CONDENSATION OR WATER WITHIN THE HEADLAMP ASSEMBLY

When dealing with customer complaints of excessive condensation and/or water within the headlamp unit, first determine if all the bulb sockets are present and correctly installed. In most cases you will find that the No. 1 and No. 2 socket covers have not been correctly installed or are missing due to improper prior repairs (i.e., customer replacing the headlamp bulbs or body shop not transferring them when replacing the headlamp unit(s) due to a collision). Any damage caused by missing socket covers is not covered by warranty.

RI 7530

