


M-TIPS



Mazda M-TIPS • Nov/Dec • 2006

2007 RX-8

Final Quality Inspection (FQI) Spark Plug Change SB 00-001/06

The spark plug set that is found in the glove compartment for the FQI procedure on 2007 RX-8s produced on or after July 14th 2006 has changed.

Previously, the spark plug set consisted of 4 spark plugs, two leading and two trailing. Beginning with July 14th 2006 production, only leading spark plug replacement is necessary for the FQI procedure. The spark plug set has been changed to include only two leading spark plugs.

Please refer to Service Bulletin 00-001/06 for updated procedures, parts and warranty information.



Year	Spark Plug Part Number	Notes
2005	N3Y3-18-S30-9U	(2) leading & (2) trailing spark plugs. Parts sent to dealers March 2006 based on 2005MY inventory.
2006-2007	N3M1-18-1BX	(2) leading & (2) trailing spark plugs. Spark plug set placed in glove compartment on production line up to VIN 207472.
2007	N3M1-18-1BXA	(2) leading spark plugs. Spark plug set placed in glove compartment on production line from VIN 207473 and later.