

2004-2008 RX-8

Warm Air From A/C Vents With Temperature Set To Cold RI4779

Some customers may experience sudden increase in vent temperature with the AC on. This may be caused by a faulty climate control unit.

To test the temperature control function of the climate control unit, perform the CLIMATE CONTROL UNIT INSPECTION as outlined in section 07-40 of the appropriate Workshop Manual. This procedure performs on-board diagnostic of the climate control unit's indicator lights, switches and the temperature control function.

NOTE:

Before diagnosing climate control unit, check for cracked temperature control dials. The dial hub may be cracked, causing the dial to free-wheel on the control unit stem. Refer to Service Bulletin 07-003/03 for more details.

