


2004-2011 RX-8 M/T ***PILOT BEARING GREASE VERIFICATION ON*** ***REMANUFACTURED ENGINES***

When installing a remanufactured engine in a 2004-2011 RX-8 M/T vehicle, verify grease is applied to the pilot bearing.



Roaring/whining type noise may occur if the pilot bearing is not properly lubricated.



Pilot bearing