

© 2005 Mazda Motor of America, Inc.

<b>Subject:</b>  REDUCTION OF TIE-DOWN PLUGS - SERVICE TIP	<b>Bulletin No:</b> 00-001/05
	<b>Last Issued:</b> 3/14/2005

## APPLICABLE MODEL(S)/VINS


2005 RX-8 (April 1, 2005 production and later)

## DESCRIPTION

On all RX-8 vehicles, there are four tie-down holes on the frame. 2 holes located at the front of the vehicle and 2 at the rear sides. All 4 tie-down holes must be plugged during pre-delivery inspection. For this purpose, 4 hole plugs are included with the vehicle in the glove box.


Beginning with April 1, 2005 production, only 2 plugs will be in the glove box. Please fit these 2 plugs to the rear side tie-down holes only, leaving the front 2 tie-down holes open. Revised instructions will be included with the 2 tie-down plugs.

PRIOR TO APRIL 1 2005  
PRODUCTION DATE



1472

APRIL 1, 2005 PRODUCTION  
DATE AND LATER



Page 1 of 1

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.