

Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



© 2004 Mazda Motor of America, Inc.

Subject: DOME LAMP FLASHING AND / OR CLICKING SOUND FROM REAR DOORS	Bulletin No: 09-007/04
	Last Issued: 3/17/2004

APPLICABLE MODEL(S) / VINS

2004 RX-8 (with Mazda Genuine Accessory theft-alarm shock sensor installed)

DESCRIPTION

Some customers may experience a concern of the dome light flashing or a clicking sound from the rear doors when a front door is closed. The cause may be an due to a missing diode in the early version of the Mazda Genuine Accessory Theft-Alarm shock sensor installed in the vehicle.

Customers having this concern should have their vehicles repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify customer complaint. Get in vehicle and close front doors (make sure rear doors are closed). Watch for dome light flashing and clicking sound from rear doors.
2. Install a Diode update kit.
NOTE: The Diode update kit includes detailed installation instructions.
3. Verify repair.

PART(S) INFORMATION

Part Number	Description	Qty.	Notes
0000-8F-K03	Diode Update Kit	1	

Page 1 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair. Refer to the SRT microfiche for warranty term information.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	64
Damage Code	9V
Part Number Main Cause	0000-8F-K03
Quantity	1
Operation Number / Labor Hours:	YY341XRX / 0.3