

<b>Subject:</b> <b>SQUEAL NOISE FROM FRONT BRAKES DURING BRAKING</b>	<b>Bulletin No:</b> 04-006/04
	<b>Last Issued:</b> 9/21/2004

## APPLICABLE MODEL(S)/VINS

2004 RX-8 - All models equipped with 18 inch wheels (12.7 inch diameter front discs)

## DESCRIPTION

Some vehicles may experience a "squeal" noise from the front brakes when braking. This may be caused by the front brake pad material.

Customers having this concern should have their vehicle repaired using the following repair procedure.

## REPAIR PROCEDURE

1. Verify customer concern.
2. Replace front brake pads with revised parts. See Workshop Manual section 04 - DISC PAD (FRONT) REPLACEMENT.
3. Verify repair.

## PART(S) INFORMATION

Part Number	Description	Qty.	Notes
F1Y2-33-23Z	Front Pad & Shim Set	1	

## WARRANTY INFORMATION

### NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair. Refer to the SRT microfiche for warranty term information. Warranty terms for this repair have been extended to 36 months from vehicle in-service date or 50,000 accrued miles which ever occurs first.
- Additional diagnostic time and rotor machining cannot be claimed for this repair.

Warranty Type	A
Symptom Code	35
Damage Code	9J
Process Number	E04001
Part Number Main Cause	F1Y2-33-23Z
Quantity	1
Operation Number / Labor Hours:	XX729XRX / 0.6 Hrs (Both Sides)