


## ***2013-2014 CX-5*** ***RATTLE NOISE FROM REAR OF VEHICLE***

Some customer may complain about a rattle type noise coming from the rear of the vehicle. This may sound like a loose liftgate latch. This may be caused by rocks in the rear lower control arm.



Remove rocks to resolve rattle noise concern.

Rocks