

2014 Mazda6 19" WHEEL REPLACEMENT

After a wheel replacement, some customers may notice a color difference on the back side of the replacement wheel. This may be caused by an incorrect part replacement. Identify the wheel supplier before ordering the new wheel(s).

There are two 19" wheel suppliers for the 2014 Mazda6:

1. LHMW
2. HITACHI METALS

Check the stamp mark on back of the wheel for correct part ordering.

LHMW

HITACHI METALS



Front

Wheels are similar in appearance. There is no identification stamp mark on the front of the wheel.



Back

Identification stamp mark is located on the back of the wheel.



LHMW stamp mark

HITACHI METALS stamp mark

