


MULTI-MODEL EXCEPT RX-8 HIGH ENGINE OIL CONSUMPTION (UPDATE)

Some customers may complain about high engine oil consumption. Before attempting any repairs, verify the complaint by using the guideline below to determine if an engine repair is necessary:

Engine Oil Consumption Inspection Guideline

1. Record the vehicle mileage.
2. Engine at normal operating temperature, top off engine oil level to the full mark on the dipstick.
3. Ask the customer to return to the dealer after 1200 miles to recheck the engine oil level.
4. After 1200 miles, engine at normal operating temperature, check the engine oil level on the dipstick .
5. Is the engine oil level above the low mark on the dipstick?
 - Yes - No repair is necessary.
 - No - Proceed to MS3 online or Workshop Manual (section 01-03 NO. 16 HIGH OIL CONSUMPTION/LEAKAGE).

Note: Workshop manuals will be revised at a later date to include this new information.



Approximately 1 liter (1.06 quart) of oil from Low mark to Full mark.

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2015 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com or fax to (949) 442-6599. If we select your repair tip, you will receive 10,000 Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration