


# M-TIPS



Mazda M-TIPS • Nov/Dec • 2005

## 2006 MX-5 RI4781


### AT Fluid - No Dipstick

2006 MX-5 vehicles equipped with the 6-Speed Automatic Transmission (SJ6A-EL) do not have a dipstick to check the transmission fluid level or condition.

Fluid level is checked by raising the vehicle on a hoist and removing the overflow plug on the transmission oil pan. Fluid is added to the transmission through the filler plug hole on the transmission case.

Detailed instructions for fluid level checking and fluid replacement are outlined in Workshop manual section 05-13 - AUTOMATIC TRANSMISSION FLUID (ATF) INSPECTION [SJ6A-EL] and AUTOMATIC TRANSMISSION FLUID (ATF) REPLACEMENT [SJ6A-EL].

**Overflow Plug**



**Filler Plug Hole**

