


M-TIPS



2004 RX-8 

Cold Weather Operation - MSP04

Remember to perform MSP04 (2004 RX-8 PCM reprogramming) on all vehicles that require updating. It is especially important for these vehicles to have the update performed before the winter months arrive, when engine “no start” or “flooding” concerns most likely occur. See detailed information pertaining to this issue outlined in Service Bulletin 01-022/04.

Mazda M-TIPS • November/December • 2004