

# MULTI-MODEL HEADLAMP ASSEMBLY REPLACEMENT CAUTION

When headlamp assembly replacement is required, make sure that the bulbs, bulb seals (socket covers), HID module seal, and bumper brackets are present and transferred from the old assembly to the new assembly.

Failing to do so will cause customer comebacks and/or expensive warranty debits.

