


2010-2011 MODELS


STEERING LOCK DELETION

On certain vehicles, the steering lock mechanism was deleted.
RI 7423

This can be verified by looking at the ignition cylinder ring bezel. For vehicles without the steering lock, the bezel will indicate "OFF" instead of "LOCK". If a vehicle does not have the steering lock mechanism, please proceed with warranty diagnosis and repairs accordingly. Do not attempt repairs, as this condition is normal and is not covered under warranty.



Equipped with Steering Lock



Not equipped with Steering Lock

For parts-related issues, refer to the EPC for applicable part numbers and production dates.