## **Service Bulletin**

Mazda North American Operations Irvine, CA 92618-2922



© 2005 Mazda Motor of America, Inc.

Subject:

RETRACTABLE KEY TRUNK RELEASE BUTTON - REVISED HOLD DOWN TIME

SPECIFICATION - SERVICE TIP

Bulletin No: 09-010/05

Last Issued: 6/22/2005

## **APPLICABLE MODEL(S)/VINS**

2005 RX-8 vehicles with VINs after JM1FE\*\*\*\*\*152491 (produced after April 1, 2005)

## DESCRIPTION

On 2005 RX-8 vehicles produced after April 1, 2005, some customers may complain of inconsistent operation of the trunk release button function on the retractable key. This service bulletin has been issued to inform that the time required to press and hold the trunk release button on the retractable key has changed (from approximately 0.05 to 0.7 seconds). When opening the trunk using the trunk release button on the retractable key, you must press and hold the trunk release button until the trunk opens. This production change has been made to prevent unintentional opening of the trunk lid when handling the retractable key.

Explain to the customer that this is normal operation and to press and hold the trunk release button to open the trunk.

