Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2004 Mazda Motor of America, Inc.

Subject: SPEEDOMETER REPLACEMENT PROCEDURE	Bulletin No:	09-026/04
	Last Issued:	07/01/2004

BULLETIN NOTE

This bulletin supersedes AD-003/97, issued 02/25/97. The APPLICABLE MODEL(S)/VINS, DESCRIPTION, REPAIR PROCEDURE information has been revised.

APPLICABLE MODEL(S)/VINS

1990-1994 323

1992-1995 MX-3

1990-2003 Protege

2002-2003 Protege5

1990-2004 Miata

1993-1995 RX-7

1990-1995 MX-6

1990-2002 626

1992-1995 929

1995-2002 Millenia

1991-1994 Navajo

1990-1998 MPV

2000-2004 MPV

2004 Mazda3

2004 RX-8

2003-2004 Mazda6

2001-2005 Tribute

1998-2004 B-Series Truck

DESCRIPTION

In accordance with Federal regulations, follow the procedure listed below when replacing a speedometer.

NOTE:

- Mazda vehicles are manufactured with tamper-proof speedometers.
- When a speedometer is replaced, the new speedometer will read zero (0) miles.
- This procedure is extremely important to accurately represent actual vehicle mileage.
- · Prior to speedometer removal, complete the information required on the "Speedometer Replace-

Page 1 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ----without permission in writing.

Bulletin No: 09-026/04	Last Issued: 07/01/2004
© 2004 Mazda Motor of America, Inc.	

ment Label".

• Labels can only be ordered through MStore, not MDCS.

REPAIR PROCEDURE

SPEEDOMETER REPLACEMENT

- 1. Order "Speedometer Replacement Labels" through MStore.
- 2. Record vehicle mileage before removing the speedometer.
- 3. Remove and replace the speedometer according to the appropriate workshop manual.
- 4. Complete the following information on the "Speedometer Replacement Label."
 - a. Mileage (before speedometer replacement).
 - b. Date of replacement.
 - c. Dealer code.

(Before Replacement)	SPEEDOMETER REPLACEMENT Mileage:
, , , , , , , , , , , , , , , , , , , ,	
Date Replaced:/// Dealer Code:	Date Replaced://
Dealer Code	

Complete Information and Install On Driver's Side "B" Pillar

- 5. Attach the completed label to the driver's side "B" pillar.
- 6. Complete the "Speedometer Replacement Record" in the vehicle's Warranty Information Booklet.

SPEEDOMETER REPLACEMENT RECORD		
Speedometer replacement on	with	miles
Dealer Name		
Dealer Signature		
After the speedometer is replaced, total milage the milage listed here to the current mileage sh		

Bulletin No: 09-026/04		Last Issued: 07/01/2004	
	© 2004 Mazda Motor of America, Inc.		

PART(S) INFORMATION

Part Number	Description	Qty.	Notes
9999-95-SPDO-97	Speedometer Replacement Labels	1 (Sheet)	Order labels through MStore only. Each sheet contains 20 labels.