Service Information

Mazda Motor Corporation

3-1, Shinchi, Fuchu-cho, Aki-gun Hiroshima 730-8670, Japan TEL: 81(82)287-5323 FAX: 81(82)287-5220



Category G	Technical		Ref. No. E055/09	Page 1 of 1
Coverage ☐ Distributor only ■ Please inform your dealers			Date Issued October 15, 2009	
Please convey this information to your ☐ Director ☐ General Manager ☐ Warranty Dept. ☐ Parts Dept. ☐ Training Dept. ☐ Field Rep.			Date Revised	
Applicable Model		Applicable Countries or Specifications		
All Models		Worldwide		

Subject: JIS/BCI Standard to CCA Conversion Chart

DESCRIPTION

When performing battery test using battery tester, it is necessary for some testers to input "CCA". Please refer to the following conversion chart to find appropriate CCA value for OE batteries. CCA: Cold Cranking Ampere

According to the following conversion chart, find appropriate CCA value from JIS or BCI standard which is printed on the label of battery.

JIS to CCA Conversion Chart

		Maximum Charging Current		
JIS Standard	CCA	Quick Charge	Slow Charge	
		30min	4hrs	
26B17L/R	225	15A	2.5A	
46B24L/R	325	25A	4.5A	
50D20L/R	306	25A	5.0A	
55D23L/R	356	30A	5.5A	
75D23L/R	520	35A	6.5A	
75D26L/R	490	35A	6.5A	
80D26L/R	582	35A	6.5A	
95D31L/R	622	40A	8.0A	
115D31L/R	782	45A	8.5A	

JIS: Japanese Industrial Standards

BCI to CCA Conversion Chart

		Maximum Charging Current		
BCI Standard	CCA	Quick Charge	Slow Charge	
		30min	4hrs	
96R	590	30A	5.5A	

BCI: Battery Council International

Shinji Kanai Manager, Technical Information Gr. Technical Service Dept. Mazda Motor Corporation 2952853504 (MC Internal Use)