

Service Information

Mazda Motor Corporation

3-1, Shinchi, Fuchu-cho, Aki-gun
Hiroshima 730-8670, Japan
TEL : 81(82)287-5323
FAX : 81(82)287-5220



Category U	Modification	Ref. No. M004/10A	Page 1 of 2
Coverage <input type="checkbox"/> Distributor only <input checked="" type="checkbox"/> Please inform your dealers		Date Issued July 16, 2010	
Please convey this information to your <input type="checkbox"/> Director <input checked="" type="checkbox"/> General Manager <input checked="" type="checkbox"/> Warranty Dept. <input checked="" type="checkbox"/> Parts Dept. <input checked="" type="checkbox"/> Training Dept. <input checked="" type="checkbox"/> Field Rep.		Date Revised July 21, 2010	
Applicable Model Mazda2 (DE) Mazda3 (BK) Mazda5 (CR) RX-8 (SE) MX-5 (NC) CX-9 (TB)		Applicable Countries or Specifications Europe	

REVISED

Subject: Establishment of A/C Compressor Assembly

Revision Note: DESCRIPTION has been revised.

DESCRIPTION

This Service Information is to inform that on some models/specs, the configuration of A/C compressor has been changed from "compressor set" (part number last 5 digits: 61-K00) to "compressor assembly" (61-450).

Note:


1. When ordering A/C compressor, **check EPC and order "61-450" (compressor assembly) if available (in accordance with PART INFORMATION).**
2. **When "61-450" is available, do NOT order "61-K00" any more.**
As "61-K00" does not contain "61-L20" (Pulley Kit) this was necessary to order separately in the past.
Therefore if "61-K00" was ordered with "61-L20" now, the order for "61-K00" could be automatically shifted to "61-450", so the order for "61-L20" would be duplicated as a result.

<Current: Compressor set>
("61-K00" consists of 1 to 5 shown below)



<New: Assembly (61-450)>

Shown below is just an example and not for any specific model.



PART INFORMATION

New		Current		Q'ty	Remark
Part Number	Part Name	Part Number	Part Name		
C236-61-450E	A/C compressor assembly	C236-61-K00D	A/C compressor	1	Mazda3 (BK)
CC29-61-450G		CC29-61-K00E		1	Mazda5 (CR)
D651-61-450G		D651-61-K00E		1	Mazda2 (DE)
F151-61-450A		F151-61-K00A		1	RX-8 (SE)
NEY1-61-450		NEY1-61-K00		1	MX-5 (NC)
TD15-61-450A		TD15-61-K00		1	CX-9 (TB)

Shinji Kanai
Manager, Technical Information Gr.
Technical Service Dept.
Mazda Motor Corporation