

Atkins Rotary Specialties  
 41026 Ski Park Rd E  
 Eatonville, WA 98328  
 360-832-1990

# Invoice

Date	Invoice #
5/17/2007	8602

Order Source
[REDACTED]

Ship To
[REDACTED]

P. O. #	Terms	Rep	Ship	Via	Customer E-mail	Customer Phone
	Credit Card	Dan	5/17/2007	Local Pickup		

Qty	Item Code	Description	Price	Amount
12.5	Labor	Labor @ \$80 . per hour	80.00	1,000.00T
6	N3H1-11-C00H-W	RX 8 Apex Seal Factory Mazda Part	39.95	239.70T
12	N3H1-11-C17A	RX 8 Side Sea Springs	4.10	49.20T
1	N3Z1-10-S60 -W	RX 8 O-Ring Gas ket Kit	220.00	220.00T
1	N3Z3-10-S50 C	RX8 Manual Gas ket Kit (O-Ring Kit Needed Also)	125.00	125.00T
1	ARE85 -W	93+ RX7, RX 8 Corner sealspring set of 12	22.00	22.00T
1	NF0 2-18-840	RX-8 OIL PUMP	85.00	85.00T
2	NF0 2-18-840	154-1305 Rx 8 new thermostat	25.00	50.00T
		Washington Sales Tax	8.80%	157.60

Returns must be made within 30 days, and must be received in new condition, with manufacturing packaging unopened. No returns or exchanges on used parts. A 20% restocking fee applies to all returns and shipping/handling fee will not be refunded. CODs returned due to non-payment must have all shipping charges paid before next order.

Join our news list to be kept up-to date on new parts, possible discounts, and coupon deals. Be the first to know when parts are in and out of stock.

Pulled _____	Inspected _____
--------------	-----------------

<b>Total</b>	\$1,948.50	
<b>Payments/Credits</b>	\$-1,948.50	
<b>Balance Due</b>	\$0.00	
Phone	Fax	atkinsrotary.com
360-832-1990	253-848-3284	pulleyboys.com