

Mazda M-TIPS • January/February • 2005

2004-2005 RX-8

Battery Replacement Service Tip

The RX-8's battery box is designed to duct fresh air around the battery, which aids in cooling to improve battery performance and reliability. Installing a larger battery than specified may restrict airflow and reduce battery life or performance. The battery box and cover are essential to insulate the battery from high engine compartment temperatures. Install battery as shown in illustration. Improper battery installation may reduce or eliminate airflow to battery.

