
2004 RX-8
 Phantom Fan Speed Indicator

Some customers may complain of the fan speed indicator not illuminating on the information display panel. A fan speed indicator can be seen on the information display panel, but will not illuminate when the fan speed dial is in positions 1-4.

The information display panel is a common part used in different models around the world. Some markets are equipped with an automatic climate control system different from the US version.

Vehicles with the automatic climate control system utilize the fan speed icon on the information display, while the non-automatic climate control system used in the US does not.

DO NOT attempt repairs for this complaint as it is a normal operating characteristic.



Mazda M-TIPS • September/October • 2004

Phantom Fan