## M-TIPS SEPTEMBER/OCTOBER 08

## 2009 MAZDA6, 2009 RX-8 SAT RADIO INSTALLATION / WATER IN TAIL LAMP RI6420

When installing the Sirius Satellite Radio kit into the 2009 Mazda6 or 2009 RX-8, be sure to follow the installation instructions exactly. When routing the antenna cable behind the right side taillight (Mazda6) or the left side taillight (RX-8), route and secure the antenna cable in place with butyl tape and pad protector halves as instructed in the included accessory instructions.

If the wire routing and pad attachment are not followed exactly, the taillight may fill with water when the vehicle is washed or exposed to rain or excessive moisture. Taillight assemblies will not be warrantied for water intrusion as a result of improper dealer installed SAT radio kits.