Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2004 Mazda Motor of America, Inc.

Subject:	Bulletin No:	01-047/04
NEW ENGINE OIL LEVEL GAUGE (DIPSTICK) - SERVICE TIP		
	Last Issued:	12/21/2004

APPLICABLE MODEL(S)/VINS

2005 RX-8 - With VINs after JM1FE*****143676


DESCRIPTION

The following changes have been carried out on RX-8's oil level gauge (dipstick).

- The material has been hardened.
- The diameter of the dipstick has been decreased from 0.12" (3.0 mm) to 0.08" (2.0 mm).
- · Dotted marks have been added to the oil level indicator.
- There is no longer a chamfer on the tip.

This service information is to inform you how to read the dotted marks on the new dipstick. These changes are also outlined in the Owner's Manual (Maintenance and Care section).

NEW OIL LEVEL GAUGE





CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.