# **Service Information**

Mazda Motor Corporation






Category <b>F</b>	Modification		Ref. No. M003/11	Page 1 of 2
Coverage □ Distributor only ■ Please inform your dealers			Date Issued March 16, 2011	
Please convey this information t ■ Warranty Dept. ■ Parts De	·	al Manager Rep.	Date Revised	
Applicable Model		Applicable Countries or Specifications		
RX-8 (SE) with APV		Worldwide (except North America)		

## Subject: Establishment of APV (Auxiliary Port Valve)

#### DESCRIPTION

APV (Auxiliary Port Valve) has been established as service part. Refer to Workshop Manual for replacement procedure.



#### PART INFORMATION

Part Number	Part Name	Q'ty	Remark	
N3H2-13B6X	VALVE ASSY-A/P/V;F	1	VIN lost 6 digits smaller than 200000	
N3H3-13B6X	VALVE ASSY-A/P/V;R	1	VIN last 6 digits smaller than 300000	
N3R1-13B6X	VALVE ASSY-A/P/V;F	1	VIN last 6 digits bigger than 200000	
N3R2-13B6X	VALVE ASSY-A/P/V;R	1	VIN last 6 digits bigger than 300000	
N3H6-13B65	BOLT-A/P/V	2	APV bolts need to be replaced.	

### WARRANTY INFORMATION

Refer to the following chart for warranty application.

Operation No.	F0140RRX		
Causal Part No.	Part number of APV used for repair		
Q'ty	1		
Labor Hours	7.6 Hrs (M/T, VIN last 6 digits bigger than 300000)		
	7.3 Hrs (A/T, VIN last 6 digits bigger than 300000)		
	7.7 Hrs (M/T, VIN last 6 digits smaller than 300000)		
	7.4 Hrs (A/T, VIN last 6 digits smaller than 300000)		
Period Covered	Normal warranty period		

Shinji Kanai Manager, Technical Information Gr. Technical Service Dept. Mazda Motor Corporation 29C2412101 (MC Internal Use)