


Category U	Technical	Ref. No. E033/05	Page 1 of 2
Coverage <input type="checkbox"/> Distributor only <input checked="" type="checkbox"/> Please inform your dealers		Date Issued December 20, 2005	
Please convey this information to your <input type="checkbox"/> Director <input checked="" type="checkbox"/> General Manager <input checked="" type="checkbox"/> Warranty Dept. <input checked="" type="checkbox"/> Parts Dept. <input checked="" type="checkbox"/> Training Dept. <input checked="" type="checkbox"/> Field Rep.		Date Revised	
Applicable Models RX-8 (FE / SE)		Applicable Countries or Specifications US & EC Spec.	

Subject: Protector Set for A/C Condenser



DESCRIPTION

In order to protect the A/C condenser from damage caused by stones kicked up while driving, a protector set has been established.



PROTECTOR INSTALLATION PROCEDURE

1. Remove the under cover.
2. Remove the bolts from the A/C condenser.
3. Install a protector in the condenser of the radiator.
Note: Align the cut portion of the upper bracket and A/C condenser to the rib of the radiator, and then tighten the bolts.
4. Reinstall the under cover.



PARTS INFORMATION

Part Number	Part Name	Q'ty
FE01-61-89Y	Protector Set	1

Note: Before fitting the protector set to the customer, please explain that the part cost and labor cost should be paid by the customer.



Koji Tsuji
Manager, Technical Information Gr.
Technical Service Dept.
Mazda Motor Corp.