


# M-TIPS



Mazda M-TIPS • January/February • 2006

**2004-2006 RX-8** RI4857

## **Broken Rear License Plate Attachment**

Some vehicles may have an instance where the attachment for mounting the rear license plate may have broken off and fallen into the bumper. As an alternative to removing the entire bumper cover to repair this issue, a normal press-in license plate mounting nut will work to attach the plate. Press the nut into the bumper and attach the plate using the existing screws.

